


CROQUIS DE UBICACION


1


1	2	3	4
5	6	7	8


SANYO


MOD: CLP 3022/6024/6029/2143/3024




















8

SANYO

MOD: CLP 3022/6024/6029/2143/3024

NOTES:

1. RESISTORS SPECIFIED WITH VALUE ARE "1/60J".
(EX. R100 10K → 1/60J 10K)
RESISTORS SPECIFIED WITH TYPE, TOLERANCE AND VALUE ARE "1/4".
(EX. R110 DJ1K → 1/4DJ 1K)
2. ALL CAPACITORS ARE 50V RATING UNLESS OTHERWISE NOTED.
3. LIST OF REPLACEABLE PARTS.

CODE	REPLACEABLE PARTS			
1S1555	1S1555	DS442	1S2473	1S2078
2SC536	2SC536 (E.F.G.)	2SC945A (P.D.R.)	2SC1815 (O.Y.G.)	2SC1740 (O.R.S.)
2SC536	2SC1740S (O.R.S.)			
2SA608	2SA608 (E.F.)	2SA564A (O.R.)	2SA933 (O.R.)	2SA933S (O.R.)
2SA608	2SA1015 (O.Y.)			