



SANYO Semiconductors NEWS

Announcement Regarding the Discontinuation of Hybrid ICs due to the Disuse of Color Aluminum Boards

Thank you for using SANYO semiconductor products.

The following SANYO semiconductor products have been discontinued.

Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

1. Discontinued products

See the affected products list below.

2. Reason for discontinuing

The circuit board used for the affected products has been discontinued.

3. Date of discontinuation

End of May 2007

Affected products list

Affected products	Replacement or similar products	Affected products	Replacement or similar products	Affected products	Replacement or similar products
STK402-020-E	STK433-030-E	STK402-700	-	STK412-040	STK415-140-E
STK402-030-E	STK433-030-E	STK402-920	STK433-930	STK412-040T	STK415-140-E
STK402-030S	STK433-030-E	STK402-920C	STK433-930	STK412-090-E	STK415-090-E
STK402-040-E	STK433-040-E	STK402-930	STK433-930	STK413-000	STK416-100-E
STK402-040S-E	STK433-040-E	STK402-930C	STK433-930	STK413-000B	STK416-100-E
STK402-050-E	STK433-060-E	STK402-940-E	STK433-940	STK413-010A	STK416-120-E
STK402-070-E	STK433-070-E	STK402-950C-E	STK433-950	STK413-010B	STK416-120-E
STK402-071-E	STK433-070-E	STK403-030-E	STK433-030-E	STK413-020A-E	STK416-120-E
STK402-070S-E	STK433-090-E	STK403-040-E	STK433-040-E	STK442-030	STK433-030-E
STK402-090S-E	STK433-090-E	STK403-070-E	STK433-070-E	STK442-050-E	STK433-060-E
STK402-100-E	STK433-100-E	STK403-240A-E	STK433-240A-E	STK442-070-E	STK433-070-E
STK402-100S-E	STK433-100-E	STK403-250A-E	STK433-260A-E	STK442-090-E	STK433-090-E
STK402-120-E	STK433-120-E	STK412-000	STK415-100-E	STK442-110-E	STK433-120-E
STK402-120S-E	STK433-120-E	STK412-000B	STK415-100-E	STK442-110I-E	STK433-120-E
STK402-230-E	STK433-230A-E	STK412-000J	STK415-100-E	STK442-120-E	STK433-120-E
STK402-240-E	STK433-240A-E	STK412-010-E	STK415-120-E	STK442-130-E	STK433-130-E
STK402-250-E	STK433-260A-E	STK412-010A	STK415-120-E	STK443-050-E	STK433-260A-E
STK402-270-E	STK433-270-E	STK412-010B	STK415-120-E	STK443-070-E	STK433-270-E
STK402-450	-	STK412-010J	STK415-120-E	STK443-090-E	STK433-290-E
STK402-480	-	STK412-020A	STK415-120-E	STK470-010A	-
STK402-500	-	STK412-020J	STK415-120-E	STK470-020A	-
STK402-650	-	STK412-020-E	STK415-120-E	STK470-040	-
STK402-680	-	STK412-030-E	STK415-130-E	STK470-050A	-

Continued on next page.

SANYO Semiconductor Co., Ltd.

TOKYO OFFICE Tokyo Bldg., 1-10, 1 Chome, Ueno, Taito-ku, TOKYO, 110-8534 JAPAN

Continued from preceding page.

Affected products	Replacement or similar products
STK470-090A	-
STK490-040	-
STK490-070	-
STK490-110	-
STK490-140	-
STK490-310	-
STK490-340	-
STK499-140	-
STK392-560	-
STK392-570	-
STK393-110	-
STK393-110-E	-

Please contact your SANYO semiconductor sales representative if you have any questions or need any technical documentation.